

Attributes control charts

- charts for defectives (np and p) based on Binomial distribution
- charts for occurrences (defects) (c and u) based on Poisson distribution

Attributes Control Charts

1

The parameters of the np chart according to the $\pm 3\sigma$ rule

$$E(x) = np$$

$$CL_{np} = n\bar{p}$$

$$Var(x) = np(1-p)$$

$$UCL_{np} = n\bar{p} + 3\sqrt{n\bar{p}(1-\bar{p})}$$

$$LCL_{np} = n\bar{p} - 3\sqrt{n\bar{p}(1-\bar{p})}$$

If LCL is < 0 , set to zero.

\bar{p} is the average proportion of defectives

Attributes Control Charts

4

Control charts for count of defectives: np chart

p is the proportion of defectives in the population (process), its estimate is the proportion of defectives in the sample :

$$\hat{p} = \frac{x}{n}$$

Attributes Control Charts

2

Example 1

50 pieces are drawn in each half an hour from a process.
Number of defectives:

time	8:00	8:30	9:00	9:30	10:00	10:30	11:00	11:30
$D(np)$	0	5	3	7	5	5	4	8

time	12:00	12:30	13:00	13:30	14:00	14:30	15:00	15:30
$D(np)$	0	5	3	7	5	5	4	8

Prepare an np chart assuming the situation of a Phase I study!

Attributes Control Charts

5

Binomial distribution:

$$p(x) = \binom{n}{x} p^x (1-p)^{n-x}$$

$$\mu_x = E(x) = np$$


$$\sigma_x^2 = Var(x) = np(1-p)$$

$$\mu_{x/n} = E\left(\frac{x}{n}\right) = p$$

$$\sigma_{x/n}^2 = Var\left(\frac{x}{n}\right) = \frac{p(1-p)}{n}$$

Attributes Control Charts

3




Why do we have a single chart?

Attributes Control Charts


6

np- chart with changing sample size



Attributes Control Charts

7



Attributes Control Charts

10

Control chart for proportion of defectives: *p* chart

$$\hat{p} = \frac{D}{n} \quad E(\hat{p}) = p \quad Var(\hat{p}) = \frac{p(1-p)}{n}$$

The parameters according to the $\pm 3\sigma$ rule:


$$CL_p = \bar{p}$$

$$UCL_p = \bar{p} + 3\sqrt{\frac{\bar{p}(1-\bar{p})}{n}} \quad LCL_p = \bar{p} - 3\sqrt{\frac{\bar{p}(1-\bar{p})}{n}}$$

Attributes Control Charts

8

using actual sizes of subgroups



Attributes Control Charts

11


time	D	n
8:00	0	40
8:30	5	48
9:00	3	55
9:30	7	62
10:00	5	51
10:30	5	50
11:00	4	45
11:30	9	40
12:00	0	38
12:30	5	42
13:00	3	57
13:30	7	63
14:00	5	41
14:30	5	58
15:00	4	50
15:30	8	45

Example 2
Prepare a *p* chart the data for!

Attributes Control Charts

9

p chart with average control limits



Attributes Control Charts

12

Control charts for occurrence of defects: c chart

Poisson distribution

for modelling rare events

x is the number of occurrences, „from among how many“ is not defined

$$p(x) = \frac{e^{-\lambda} \lambda^x}{x!}$$

Expected value and variance: $E(x) = Var(x) = \lambda$

λ is the expected number of occurrences in a unit

Attributes Control Charts

13

sample	# defects
1	17
2	14
3	15
4	13
5	7
6	12
7	17
8	12
9	16
10	2

Example 3

The average number of painting defects on car doors manufactured is 2. The doors are sampled for checking, 6 doors are considered as a sample. Prepare a c chart for checking stability of the process!

Phase I or Phase II?

Attributes Control Charts

16

Defect charts: c chart

$$p(x) = \frac{\lambda^x e^{-\lambda}}{x!} \quad \lambda = np$$


$$E(x) = \lambda \quad Var(x) = \lambda$$

The x average number of defects obtained in Phase I is the estimate of the λ parameter :

$$\bar{c} = \frac{\sum_{i=1}^m c_i}{m} \quad \begin{array}{l} c_i \text{ \# of defects found in sample } i \\ m \text{ \# of samples checked} \end{array}$$

Attributes Control Charts

14



Attributes Control Charts

17

In Phase II (on-going control) the parameters of the charts using the $\pm 3\sigma$ rule:

$$CL_c = \bar{c}$$

$$UCL_c = \bar{c} + 3\sqrt{\bar{c}}$$


$$LCL_c = \bar{c} - 3\sqrt{\bar{c}}$$

\bar{c} is the value obtained in Phase I.

Attributes Control Charts

15

Considering as Phase I study:



Attributes Control Charts

18

Example 4

The average number of unanswered calls in a call center is 2 per hour (from earlier studies). Each week 6 hours are checked and considered as 1 sample. Prepare a c chart for checking stability of the process!

week	# unanswered
1	17
2	14
3	10
4	13
5	7
6	12
7	17
8	12
9	16
10	2

Phase I or Phase II?

Attributes Control Charts

19

Comparison of variables and attributes control charts

variables: continuous random variable


attributes: discrete random variable

The variables charts:

- offer more information, more sensitive to changes, the signal the special causes (e.g. shift) before defectives are manufactured, since the specification limits are not necessarily reached when control limits are exceeded.
- require much smaller sample size, but the measurement is usually more expensive than deciding on attributes, and the former is not always applicable.

Attributes Control Charts

22



Attributes Control Charts

20

variables data

data collected in groups: \bar{X} -bar/R

individual data: I/MR, X/MR

attribute data

nonconforming items

sample size is constant: np or p

sample size is changing: np or p

defects

sample size is constant: c

sample size is changing: u

Attributes Control Charts

23

Control charts for occurrence of defects: u chart

The size of the sample may not be constant

E.g.

- the car doors may not be of the same type,
- the number of pieces on days are different
- the complexity of bills may be different,
- the number of calls on different days is different

Attributes Control Charts

21